**1**

TILT VESA MOUNTING PLATE


2

REMOVE RUBBER CAP



3

REMOVE COVER PANEL

4

REMOVE RUBBER CAPS

5

ASSEMBLE WINGS AS SHOWN - L TO L AND R TO R USING 4 NUTS (PROVIDED)

6

TURN PRINTER TRAY - ENSURE IT IS AS PER BELOW

TOP VIEW

LEFT SIDE   RIGHT SIDE

7

SLIDE PRINTER TRAY ONTO THE BRANDME STAND

8
SELECT FROM HEIGHT OPTIONS

9
TIGHTEN 4 SCREWS AND
NUTS (PROVIDED) - 2 PER SIDE

10
REPLACE COVER PANEL
AND THEN REPLACE RUBBER CAP

11

In The Box

M4 Nuts

M4X10mm Screws

Right Wing

Left Wing

Printer Tray Body